

# ELECTRICAL<sup>vol. 3</sup> MACHINES


---

A. IVANOV-SMOLENSKY



Mir Publishers Moscow

А. В. Иванов-Смоленский  
ЭЛЕКТРИЧЕСКИЕ МАШИНЫ



Издательство «Энергия» Москва

# ELECTRICAL MACHINES

A. IVANOV-SMOLENSKY

Vol.

3

Translated from Russian  
by BORIS V. KUZNETSOV

MIR Publishers      Moscow

First published 1983

Revised from the 1980 Russian edition

*На английском языке*

© Издательство «Энергия», 1980 г.

© English translation, Mir Publishers, 1983

# Contents



## Direct-Current and Alternating-Current Commutator Machines

<b>Chapter 64</b>	<b>Direct-Current Electrical Machines</b>	<b>9</b>
64-1	Purpose and Applications	9
64-2	A Brief Historical Outline	10
64-3	Construction and Principle of Operation	13
64-4	Armature Windings	17
64-5	Armature EMF	30
64-6	Electromagnetic Torque	38
64-7	MMFs and Resistances of the Windings of a D.C. Machine	40
64-8	Calculation of the Magnetic Circuit at No Load	43
64-9	Calculation of the Magnetic Circuit and Voltage On Load	48
64-10	Energy Conversion by a D.C. Machine	56
64-11	Commutation	59
64-12	D.C. Generators	70
64-13	D.C. Motors	84
64-14	A Brief Outline of Soviet-Made D.C. Machines	96
<b>Chapter 65</b>	<b>Special-Purpose D.C. Machines</b>	<b>100</b>
65-1	Permanent-Magnet D.C. Machines	100
65-2	The Krämer D.C. Generator	102
65-3	The Split-Pole Generator	102
65-4	The Rosenberg Variable-Speed Generator	104
65-5	Rotary Power Amplifiers	107
65-6	Round-Armature and Printed-Armature Motors	110
65-7	Acyctic or Homopolar Machines	111
65-8	Magnetohydrodynamic (MHD) D.C. Machines	113
<b>Chapter 66</b>	<b>Rotary Converters</b>	<b>115</b>
66-1	Motor-Generators Sets	115
66-2	D.C.-to-D.C. Dynamotors	116
66-3	A.C.-to-D.C. Dynamotors	118
<b>Chapter 67</b>	<b>Solid-State Commutator D.C. Machines</b>	<b>121</b>
67-1	Replacement of the Mechanical Commutator	121

67-2	Fractional-HP Transistor D.C. Motors	124
67-3	Thyristor-Commutated, Closed-Winding D.C. Motor	130
<b>Chapter 68</b>	<b>Alternating-Current Commutator Machines. Speed Control Systems Using Auxiliary Machines</b>	<b>134</b>
68-1	Commutator Action in A.C. Machines	134
68-2	The Commutator as a Frequency Changer	135
68-3	Three-Phase A.C. Commutator Motors	139
68-4	Speed and Power Factor Control Schemes for Induction Motors	148
68-5	Single-Phase Commutator Motors	155

# 7

## Transient Phenomena in Electrical Machines

Introduction		165
Chapter 69	Mathematical Description of Transients in Induction Machines	166
69-1	Differential Equations Based on Phase Quantities	166
69-2	Zero-Sequence Components of the Phase Quantities	170
69-3	Phase Quantities in Terms of Resultant Phasors	174
69-4	The $\alpha$ - and $\beta$ -Axis Components of Stator Quantities and the $d$ - and $q$ -Axis Components of Rotor Quantities	176
69-5	The $d$ - and $q$ -Axis Components of Stator Quantities and the $\alpha$ - and $\beta$ -Axis Component of Rotor Quantities	178
69-6	Flux Linkage Phasors in Terms of Current Phasors	179
69-7	The Voltage Equation in Terms of the $\alpha$ - and $\beta$ -Axis Components	181
69-8	Voltage Equations in Terms of $d$ - and $q$ -Axis Components and in Terms of Components Along Axis Rotating at Arbitrary Velocity. Equivalent Circuits	183
69-9	Electromagnetic Torque Expressed in Terms of Resultant Current and Flux Linkage Phasors and Their Components	186
69-10	Equations of a Three-Phase Induction Machine in a Balanced Steady State	188
Chapter 70	Transient Phenomena in Induction Machines	191
70-1	Introductory Remarks	191

- 70-2 Transients with the Stator Winding Open-Circuited. Disconnection of an Induction Machine from the External Circuit 193
- 70-3 Transients with the Stator Winding Short-Circuited or Connected to an External Line 195
- 70-4 Switch-On of an Induction Machine 203
- 70-5 Transients during a Balanced Short-Circuit in the Stator Winding of an Induction Machine 210

## **Chapter 71 Mathematical Description of Transient and Asynchronous Conditions in Synchronous Machines 212**

- 71-1 Statement of the Problem. Simplifying Assumptions 212
- 71-2 Equivalent Circuits for the Damper Winding 213
- 71-3 Referring the Rotor Circuits to the Stator Side 216
- 71-4 Resistive and Inductive Parameters of a Salient-Pole Synchronous Machine with Referred Rotor Circuits 218
- 71-5 Circuit Voltage Equations in Terms of Phase Quantities 224
- 71-6 Circuit Voltage Equations in the  $d, q$ -Plane 226
- 71-7 Electromagnetic and the Equation of Motion for the Rotor 232
- 71-8 Equations of a Three-Phase Synchronous Machine in a Balanced Synchronous Steady State 233

## **Chapter 72 Transients in Synchronous Machines Caused by Changes in and Suppression of Field Excitation 235**

- 72-1 General Remarks 235
- 72-2 Transients in a Synchronous Machine with No Damper Winding (with the Stator Winding Open-Circuited) 235
- 72-3 Transients in a Synchronous Machine with a Damper Winding and with the Stator Open-Circuited 239
- 72-4 Transients in a Synchronous Machine without a Damper Winding, with the Stator Short-Circuited 247
- 72-5 Transients in a Synchronous Machine with a Damper Winding and the Stator Winding Short-Circuited 250

## **Chapter 73 Transients Caused by a Balanced Short-Circuit on the Stator Winding of a Synchronous Machine 253**

- 73-1 General Remarks. Initial and Terminal Conditions 253

73-2	Equations for Transient Currents	256
73-3	Periodic Currents	257
73-4	Aperiodic Current Components	265
73-5	Total Short-Circuit Currents in the $d$ - and $q$ -Axis Stator Circuits	268
73-6	Currents in the Stator Phases	269]
73-7	Currents in the Rotor Windings	272]
<b>Appendix.</b>	Conductor Materials for Electrical Machines and Transformers	277
Bibliography		278
Index		279

---

# Direct-Current and Alternating-Current Commutator Machines

---



---

## 64 Direct-Current Electrical Machines

### 64-1 Purpose and Applications

This part of the book will be concerned with electrical machines connected to the external circuit via what is known as the *commutator*.

The function of a commutator is to convert a.c. to d.c. in the generating mode and to invert d.c. to a.c. in the motoring mode. A commutator, in one form or another, is built into any d.c. machine because its armature winding must carry a.c.—it is only then that there will be a continuous and unidirectional energy conversion.

The most commonly used form of commutator is the *mechanical commutator*—a mechanical rectifier-inverter connected between the armature coils and the d.c. terminals. Quite aptly, such machines are called *commutator d.c. machines*. Recently, there has been a growing trend towards using electronic (or solid-state) commutators—switching arrangements based on thyristors, rectifying diodes, or transistors—to supplement or supplant the mechanical commutator function.

Unless otherwise qualified, the term “commutator d.c. machine” will refer to those fitted with a mechanical commutator. As already noted, they may be motors or generators.

**D.C. motors.** Direct-current motors have a broad range of speed control coupled with a high efficiency over the range, and can be built with torque-speed characteristics to suit any particular applications. This is why, although they are twice or three times more expensive to make than squirrel-cage induction motors, d.c. motors are preferable wherever their special qualities are desirable or decisive. For example, they are widely used in electric traction on

railways where their drooping torque-speed characteristic and wide range of speed control are valuable. The same goes for the d.c. motors used in cranes and other hoisting equipment. Large d.c. motors (up to 12 MW) are used as drives in blooming and slabbing mills, as main propulsion units on Diesel-electric ships. In most cars, tractors and aircraft using d.c. electric supply, all auxiliaries are driven by d.c. motors. Small d.c. motors (from a fraction of a watt to tens of watts) are employed in various automatic control applications.

Direct current for d.c. motors is supplied by d.c. generators, a.c.-to-d.c. converters or rectifiers.

**D.C. generators.** Direct-current generators supply d.c. for industrial purposes where low voltage is required (electrolysis, electroplating, and the like). In many cases, they serve as exciters for synchronous generators.

There are also various special-purpose d.c. generators (welding, train-lighting), d.c. rotary amplifiers (control generators), etc.

## ☆ 64-2 A Brief Historical Outline

In 1821, Faraday demonstrated a device in which a conductor carrying d.c. rotated around a magnet. In fact, his device was a primitive homopolar machine. In the years that followed, several more devices capable of converting electrical energy to mechanical were made. In 1824, Barlow described a device resembling a homopolar machine, in which a copper disc placed in the field of a permanent magnet would rotate when supplied with current.

In 1833, Ritchie described the first working model of a heteropolar commutator motor. In his device, the field was excited by a horse-shoe magnet between the poles of which there was an electromagnet fed with d.c. via the commutator. A unidirectional torque was produced by the interaction of the permanent magnet and the electromagnet in which the direction of current flow was reversed in a periodic fashion.

In 1834, Jacobi built an electromagnetically excited d.c. motor which could be used as a drive for various machines. It had two groups of U-shaped magnets, with four magnets per group. One group was mounted on a stationary frame, and the other on a rotating disc, so that the two

groups faced each other. The coils of all the magnets were connected in series (today, we would call it "series-excited" or "series-wound"). Direct current was supplied by a battery of primary cells. The polarity of the rotating magnets was periodically changed by a commutator. In 1838, Jacobi built a better and larger motor which could propel a small boat. In fact, it was a combination of 40 small units each of which differed from the machine of 1834 only in that the axes of the rotating and stationary magnets were arranged radially and in the same plane. A major limitation of Jacobi's motor was the pulsating torque, because both the armature and the field structure used a salient-pole core.

In 1859, Pacinotti built an electric motor which had a nonsalient-pole, distributed-winding armature and produced a practically constant torque. The armature core was a toothed steel ring mounted on the shaft by means of brass spokes. The slots received coils brought out to commutator bars. The commutator had as many bars as there were armature coils. Current was conveyed to the commutator bars by contact rolls. Placed across from the armature teeth were two electromagnets of opposite polarity, fitted with pole-pieces. The electromagnets were connected in series with the armature winding and took a small current for excitation (owing to the teeth on the armature core). For all of its advantages, Pacinotti's motor failed to become a practical machine because, like Jacobi's motor, it required an economical d.c. source which was nonexistent at that time.

Direct-current generators lagged behind d.c. motors at all times. For the first time, Faraday thought of building a homopolar d.c. generator in the form of a disc rotating in a magnetic field in 1831, that is, a decade after he had built his homopolar motor. In 1832, the Pixie brothers built a heteropolar d.c. generator employing a commutator for rectification of the alternating current induced in stationary coils mounted on a U-shaped iron core. The field in the core was periodically reversed in polarity by a rotating U-shaped magnet placed opposite to the core.

For practical purposes, a permanent-magnet d.c. generator was first used by Jacobi in 1842. In contrast to the Pixii machine, the magnets were stationary and the coils were rotating. In the 1840-50s, some prominence was gained by Störer's permanent-magnet generator with three rotating

magnets. For larger output, several such machines would be combined into a single assembly. From 1856 to 1865, permanent-magnet generators of this design were produced by the Alliance Company (France). They were driven by a steam engine with a power output of 6 to 10 hp.

In 1851, Sinsteden proposed to replace the permanent magnets by electromagnets energized from another permanent-magnet generator. This idea was embodied, for example, in 1863 in Wilde's generator which was built in two modifications, as a single-phase a.c. generator (see Sec. 51-2) and as a d.c. generator. In the d.c. generator, a.c. was rectified by a simple commutator. The excitation field was produced by a U-shaped electromagnet whose pole-pieces encircled a concentrated-winding, salient-pole armature. The voltage at the brushes was a pulsating one.

In 1854, Hjort took out a patent for a self-excited machine. For "initial" excitation, he proposed to use permanent magnets, so his machine actually used a combination of excitation.

In 1856, Jedlik came out with the idea to use residual magnetization for self-excitation; in 1861, he built a self-excited d.c. generator based on his idea.

In 1866, Siemens applied self-excitation to series-wound generators—a feature which made them attractive as sources of direct current for lighting.

However, d.c. generators remained unattractive commercially until 1870 when Gramme took out a patent for a self-excited generator with a ring-shaped armature and a toroidal winding divided into a multiplicity of coils brought out to the bars of a commutator of a nearly present-day design.

Although the Gramme ring armature was basically similar to Pacinotti's invention made in 1860, it differed in two important aspects: the ring core was made of a bundle of iron wires (as a way of reducing eddy-current losses) and had no teeth (which was a step backward from Pacinotti's idea and could not but lead to an increased reluctance of the magnetic circuit). Its advantages were obvious (a practically constant terminal voltage, freedom from an additional excitation source, a relatively smaller weight, and high efficiency), and the Gramme generator quickly ousted all the other types. At that time, the principle of reversibility had been well established, and the Gramme

machine came to be used as both generator and motor.

In 1873, von Hefner-Altenneck and Siemens replaced the ring armature by a drum design in which both sides of each coil contributed to the output emf. In 1878, it was proposed to cut slots in the drum armature core, and this substantially reduced the radial gap length.

In 1879, Siemens used a series-wound generator to power the first electric railway demonstrated at the Berlin Exhibition.

In 1880, Edison proposed to build up the armature core of insulated iron laminations—a feature which led to a sizeable reduction in eddy-current losses and armature reaction. In 1884, it was proposed to add a compensating winding, and in 1885, commutating (or intermediate) poles as a way of reducing armature reaction still more and improving commutation. Thus, towards the end of the past century the d.c. machine had become almost what it is today.

### 64-3 Construction and Principle of Operation

As has been noted in Sec. 64-1, we shall deal with d.c. machines, that is, those connected to a d.c. system via a mechanical rectifier-inverter or, simply, a *commutator*.

To simplify the commutator design, the machine must be of inverted construction, that is, its d.c.-fed field winding must be on the stator, and the armature (output) winding on the rotor. With this arrangement, the commutator is mounted on the rotor and consists of a multiplicity of bars or segments to which the terminal leads of the armature coils are taken, and a set of stationary brushes held in contact with the commutator bars.

(a) **Construction.** In sketch form, the construction of a d.c. machine is shown in Fig. 64-1. Referring to Fig. 64-2, the stator consists of a yoke (or frame) 6, the cores of main poles 1 and commutating (or intermediate) poles 3, and the field coils encircling the poles. The number of main poles depends on the power rating and rpm. As a rule, four or six main poles are provided. Fractional-hp machines have two main poles, and very large machines up to several tens. Figure 64-2 shows the stator of a four-pole machine. The main-pole cores are built up of structural-steel sheet



laminations 1 or 2 mm thick, clamped together by studs 8. Attachment of the poles to the yoke is by studs 9 screwed into the cores, and nuts 10. The compole cores are solid pieces of iron attached to the yoke by bolts 4.

The main poles carry the coils of one or several field windings (the series field winding 2 is traversed by the rectified armature current, the shunt field winding 7 is connected to the armature brushes and energized from an external d.c. supply). The compole coils are connected in series with the armature winding.




Fig. 64-5 Connection of armature coils to the commutator

As is seen from Fig. 64-3 the armature core consists of one or several blocks, 2, of varnish-insulated electrical-sheet steel laminations 0.5 mm thick. The blocks are separated by radial ventilation ducts (not shown in the figure). The core laminations and blocks are clamped together by rings 1 and 3 which also double as coil-holders. The core armature may be mounted either directly on the shaft, 4, or on a spider. If the outer diameter of the core exceeds 100 cm, it is assembled of segments.

The slots on the armature core receive the insulated coils of a two-layer armature winding, with the lower sides nearer to the bottom, and the upper sides nearer to the top of the slots (Fig. 64-4). As shown in Fig. 64-5, the terminal leads,

4 and 6, of the coils are soldered to risers 3 on the commutator bars 1. The centrifugal force of the leads is taken up by a wire binding 5. The terminal lead 6 from the lower side of one coil is connected to the terminal lead 4 of the upper side in another coil, and all the coils are interconnected so as to form a closed winding (for the winding circuits, see Sec. 64-4).

The commutator (Fig. 64-5) is an assembly of copper bars or segments 1. The bars are insulated from one another by mica (or micanite) spacers 12 and from the ground by tapered or cylindrical micanite washers 2. The commutator-bar assembly is held together by a commutator shell 8 and Vee-rings 7 and 11. In turn, the Vee-rings are held in place by a nut 10. The commutator assembly is press-fitted on the shaft 9 and its outer surface is machined together with the bearing seats. In this way, the commutator is given a regular cylindrical shape.




Fig. 64-6 Brush holder:  
1—brush; 2—box; 3—spring;  
4—brush-finger clamp; 5—  
pig-tail; 6—rocker

Electric connection between the armature winding and the external d.c. circuit is by means of brushes held in brush holders (Fig. 64-6). The brush holders are so built that the brush pressure can be adjusted at will and automatically maintained at a constant value as the brushes wear.

Tangentially, a brush usually spans two or three commutator bars. Axially, the length of a brush does not exceed 3 or 4 cm. Therefore, in order to obtain a safe current density at the sliding contact, it is usual to mount several brush holders on one brush finger. The total number of brush fingers is equal to the number of poles (one half is in positive polarity, and the other, in negative polarity). The brush fingers are secured in and insulated from a rocker arm by insulating sleeves. In turn, the rocker arm is fastened to the end-shield or yoke (in the case of machines with pedestal bearings). The brush fingers of the same polarity are interconnected by brush shunts.