



# High Temperature Deformation and Fracture of Materials

## 材料的高温变形与断裂

Jun-Shan Zhang



Science Press  
[www.sciencep.com](http://www.sciencep.com)

The energy, petrochemical, aerospace and other industries all require materials able to withstand high temperatures. High temperature strength is defined as the resistance of a material to high temperature deformation and fracture. This important book provides a valuable reference to the main theories of high temperature deformation and fracture and the ways they can be used to predict failure and service life.

Part I reviews the mechanisms of high temperature deformation in metals, alloys, metal matrix composites and intermetallic compounds. It discusses creep behaviour such as dislocation and recovery as well as superplastic deformation, diffusional and multiaxial creep. Part II discusses high temperature fracture, starting with the nucleation and growth of creep cavities before analysing creep crack growth and damage. Later chapters review ways of predicting creep rupture, creep-fatigue interactions and modelling service life.

*High Temperature Deformation and Fracture of Materials* will be an important reference for both academic researchers and those industry using these high temperature materials.

Professor Jun-Shan Zhang works within the School of Materials Science and Engineering at Dalian University of Technology, China.

ISBN 978-7-03-027540-0



9 787030 275400 >

定价: 88.00 元

**High Temperature Deformation  
and Fracture of Materials**

**材料的高温变形与断裂**

Jun-Shan ZHANG

张俊善 著

**科学出版社**

北 京

## 内 容 简 介

本书内容分两篇共 25 章。上篇为高温变形篇,包括金属与合金蠕变的宏观规律、蠕变位错亚结构、纯金属蠕变、固溶体合金蠕变、第二相粒子强化合金蠕变、扩散蠕变、超塑性以及多轴蠕变等内容,重点论述蠕变过程中位错与各种晶体缺陷的交互作用、蠕变微观机制以及蠕变物理模型和理论。下篇为高温断裂篇,包括蠕变空洞形核和长大、蠕变裂纹扩展、蠕变损伤与断裂的评价与预测、高温低周疲劳断裂、蠕变疲劳交互作用以及材料的高温环境损伤等内容,从微观、宏观和唯象三个层次论述了高温断裂理论及其工程应用。

本书可作为高等院校材料学科研究生教学参考书,也可供材料、固体物理和力学专业教师及科研人员参考。

### 图书在版编目(CIP)数据

材料的高温变形与断裂=High Temperature Deformation and Fracture of Materials: 英文/张俊善著. —北京:科学出版社,2010

ISBN 978-7-03-027540-0

I. 材… II. 张… III. ①材料-高温变形-研究-英文 ②材料-断裂-研究-英文 IV. TB303

中国版本图书馆 CIP 数据核字 (2010) 第 084363 号

责任编辑:姚庆爽/责任校对:刘小梅

责任印制:赵博/封面设计:耕者设计工作室

科学出版社出版

北京东黄城根北街 16 号

邮政编码:100717

<http://www.sciencep.com>

中国科学院印刷厂印刷

科学出版社发行 各地新华书店经销

\*

2010 年 7 月第 一 版 开本: B5 (720×1000)

2010 年 7 月第一次印刷 印张: 24

印数: 1—1 500 字数: 483 800

定价: 88.00 元

(如有印装质量问题,我社负责调换)

## Author contact details

---

Professor Jun-Shan Zhang  
School of Materials Science and Engineering  
Dalian University of Technology  
Dalian 116085  
CHINA

E-mail: [zjshan@dlut.edu.cn](mailto:zjshan@dlut.edu.cn)

Many structural components used in the industrial facilities for energy resources, petrochemical, aeronautical and aerospace engineering are operating at high temperatures. For instance, the vapor temperature in a thermal power station is about 600 °C; the temperatures for hydrogen production and ethylene-cracking are as high as 950 °C and 1050 °C, respectively; and the working temperatures of turbine blades in an aircraft exceed 1000 °C. High temperature strength is therefore the major concern of these materials.

High temperature strength is defined as the resistance of a material to high temperature deformation and fracture. The definition of high temperature is the temperatures at which the atomic diffusion is fast enough to affect significantly the plastic deformation and fracture behaviors of materials. Usually, for metallic alloys the temperatures considered are higher than one half of their melting points ( $T_m$ ). Atomic diffusion is a time-dependent process; hence the deformation and fracture of materials at high temperatures are related to the duration of loading. Therefore, time-dependent parameters, the strain rate and the fracture life, must be introduced in describing the high temperature strain-stress behavior of materials. In the description of the room temperature mechanical behaviors of metallic alloys, the duration of loading plays rather a less important role. In addition, the chemical or electrochemical reaction kinetics can be very fast at high temperatures. The description, in order to be reliable, has to be made by taking the high temperature environmental properties of materials into consideration.

High temperature deformation and fracture is truly an interdisciplinary subject. The many theories developed for high temperature deformation and fracture are mainly based on dislocation and diffusion, but every stage of their development resorts to the fundamental principles of solid state physics, physical metallurgy, elastic-plastic mechanics, fracture mechanics and damage mechanics, and so forth. High temperature deformation and fracture has long been one of the most active research topics in materials science and engineering. Since the 1970s, remarkable progress has been achieved in developing the relevant microscopic models and theories. In the mean time, research and development activity has also been extensively carried out on new high temperature materials such as intermetallic compounds, ceramics, polymers and com-

posite materials, and ample experimental data have been documented. The idea of writing this book grew out of an attempt for a systematic survey of the research results obtained in the high temperature deformation and fracture community during the past four decades.

In this book, we describe the general macroscopic behaviors of high temperature deformation and fracture shown by various materials, and introduce the mechanisms proposed at two microscopic length scales, i. e. , the atomic and the dislocation levels. Emphasis is placed on the models and/or theories that bridge the microscopic mechanisms and the general macroscopic properties successfully.

This book has 25 chapters and is divided into two parts. Part I (chapters 1-12) is devoted to high temperature deformation. The contents cover topics about the macroscopic high temperature deformation behaviors of metals and alloys; the development of the substructures during creep; the creep of pure metals, solid solution alloys, particle strengthened alloys and intermetallic compounds; diffusion creep; superplasticity and the multiaxial creep behaviors. Part II (chapters 13-25) covers high temperature fracture, where the creep cavity nucleation and growth, the creep crack propagation, the evaluation and prediction for creep damage and fracture, the creep-fatigue interactions, and the high temperature environmental damage of materials are discussed.

The Chinese version of this book was intended to be a reference book for our graduate students and young researchers. The motivation for publishing this book is to facilitate young students and researchers to catch on quickly the basic ideas of high temperature strength theories and the recent progresses. Considering this we choose the most typical models proposed at each stage of the development of high temperature strength theories. We present the theoretical framework of these models, rather than making comprehensive comments on the huge amount of experimental data, whether they are supporting or contradicting the theories. A comprehensive bibliography has not been attempted in the Chinese version of this book, and the references quoted in the English version are out of the same consideration.

The publication of the Chinese version of this book was financially supported by a science publishing fund of Chinese Academy of Sciences and by a publishing fund of the Dalian government.

Prof. Shouyi Gao carefully reviewed the manuscript of the Chinese version of the book. I appreciate his valuable comments and suggestions on it. My thanks are also due to my colleagues who have deeply involved in the English translation work. A non-exhaustive list would certainly include Dr. Yingmin Wang, Dr. Hao Huang, Dr. Fumin Xu, Dr. Guoqing Chen, Dr. Xiaopeng Zhu, Dr. Aimin Wu, Dr. Honggang Dong, Dr. Xiao Ren, Prof. Liangming Peng and Prof. Qing Zhou. I acknowledge the assistance of Prof. Mingkai Lei, Prof. Yi Tan and Prof. Wenlong Zhou for the organization of

the translation work. I am grateful to Dr. Weixing Chen at the University of Alberta of Canada, and Dr. Yuyuan Zhao at the University of Liverpool of the UK who revised Part I and Part II of the English version, respectively. Without the help of these colleagues and friends, the project would have never been finalized.

I thank my wife, Qide Nan, for her patience and encouragement while I am working on the book at weekends and holidays. Her faithful love was, and still is a great source of confidence.

Finally, I would like to point out that I am responsible for all the errors or deficiencies that should unavoidably remain in this book.

Jun-Shan ZHANG  
Dalian

# Contents

---

<i>Author contact details</i>	<i>xi</i>
<i>Preface</i>	<i>xiii</i>
<b>Part I High Temperature Deformation</b>	
1 Creep Behavior of Materials	3
1.1 Creep Curve	3
1.2 Stress and Temperature Dependence of Creep Rate	4
1.3 Stacking Fault Energy Effect	9
1.4 Grain Size Effect	10
References	12
2 Evolution of Dislocation Substructures During Creep	14
2.1 Parameters of Dislocation Substructures and Their Measurements	14
2.2 Evolution of Dislocation Substructure during Creep	16
2.3 Dislocation Substructure of Steady State Creep	19
2.4 Inhomogeneous Dislocation Substructure and Long-Range Internal Stress	22
References	26
3 Dislocation Motion at Elevated Temperatures	28
3.1 Thermally Activated Glide of Dislocation	28
3.2 Measurement of Internal Stress	31
3.3 Climb of Dislocations	33
3.4 Basic Equations of Recovery Creep	36
3.5 Mechanisms of Recovery	37
References	38
4 Recovery-Creep Theories of Pure Metals	40
4.1 Introduction	40
4.2 Weertman Model	41
4.3 Models Considering Sub-Boundary	42

## vi Contents

4.4	Models Based on Dislocation Network	47
4.5	Creep Model Based on the Motion of Jogged Screw Dislocation	50
4.6	Summary of Recovery Creep Models	52
4.7	Soft and Hard Region Composite Model	53
4.8	Harper-Dorn Creep	58
	References	66
5	Creep of Solid Solution Alloys	69
5.1	Interaction Between Dislocation and Solute Atom	69
5.2	Creep Behavior of Solid Solution Alloys	72
5.3	Viscous Glide Velocity of Dislocations	76
5.4	Creep Controlled by Viscous Glide of Dislocations	78
	References	81
6	Creep of Second Phase Particles Strengthened Materials	83
6.1	Introduction	83
6.2	Arzt-Ashby Model	85
6.3	Creep Model Based on Attractive Particle-Dislocation Interaction	88
6.4	Interaction of Dislocation with Localized Particles	91
6.5	Mechanisms of Particle Strengthening	93
6.6	Grain Boundary Precipitation Strengthening	96
	References	100
7	Creep of Particulates Reinforced Composite Material	102
7.1	Creep Behavior of Particulates Reinforced Aluminium Matrix Composites	102
7.2	Determination of Threshold Stress	104
7.3	Creep Mechanisms and Role of Reinforcement Phase	105
	References	110
8	High Temperature Deformation of Intermetallic Compounds	111
8.1	Crystal Structures, Dislocations and Planar Defects	111
8.2	Dislocation Core Structure	115
8.3	Slip Systems and Flow Stresses of Intermetallic Compounds	120
8.4	Creep of Intermetallic Compounds	126
8.5	Creep of Compound-Based ODS Alloys	133
	References	136
9	Diffusional Creep	139
9.1	Theory on Diffusional Creep	139
9.2	Accommodation of Diffusional Creep: Grain Boundary Sliding	142
9.3	Diffusional Creep Controlled by Boundary Reaction	144
9.4	Experimental Evidences of Diffusional Creep	149

References	151
10 Superplasticity	154
10.1 Stability of Deformation	154
10.2 General Characteristics of Superplasticity	155
10.3 Microstructure Characteristics of Superplasticity	158
10.4 Grain Boundary Behaviors in Superplastic Deformation	160
10.5 Mechanism of Superplastic Deformation	161
10.6 The maximum Strain Rate for Superplasticity	167
References	170
11 Mechanisms of Grain Boundary Sliding	172
11.1 Introduction	172
11.2 Intrinsic Grain Boundary Sliding	172
11.3 Extrinsic Grain Boundary Sliding	174
References	180
12 Multiaxial Creep Models	182
12.1 Uniaxial Creep Models	182
12.2 Mutiaxial Creep Models	183
12.3 Mutiaxial Steady State Creep Model	185
12.4 Stress Relaxation by Creep	186
References	187
<b>Part II High Temperature Fracture</b>	
13 Nucleation of Creep Cavity	191
13.1 Introduction	191
13.2 Nucleation Sites of Cavity	192
13.3 Theory of Cavity Nucleation	195
13.4 Cavity Nucleation Rate	196
References	197
14 Creep Embrittlement by Segregation of Impurities	199
14.1 Nickel and Nickel-Base Superalloys	199
14.2 Low-Alloy Steels	202
References	205
15 Diffusional Growth of Creep Cavities	206
15.1 Chemical Potential of Vacancies	206
15.2 Hull-Rimmer Model for Cavity Growth	207
15.3 Speight-Harris Model for Cavity Growth	211
15.4 The role of Surface Diffusion	213

References	215
16 Cavity Growth by Coupled Diffusion and Creep	217
16.1 Monkman-Grant Relation	217
16.2 Beer-Speight Model	218
16.3 Edward-Ashby Model	221
16.4 Chen-Argon model	222
16.5 Cocks-Ashby Model	225
References	228
17 Constrained Growth of Creep Cavities	230
17.1 Introduction	230
17.2 Rice Model	230
17.3 Raj-Ghosh Model	233
17.4 Cocks-Ashby Model	235
References	238
18 Nucleation and Growth of Wedge-Type Microcracks	239
18.1 Introduction	239
18.2 Nucleation of Wedge-Type Cracks	240
18.3 The Propagation of Wedge-Type Cracks	242
18.4 Crack Growth by Cavitation	244
References	246
19 Creep Crack Growth	247
19.1 Crack-Tip Stress Fields in Elastoplastic Body	247
19.2 Stress Field at Steady-State-Creep Crack Tip	251
19.3 The Crack Tip Stress Fields in Transition Period	255
19.4 Vitek Model for Creep Crack Tip Fields	259
19.5 The Influence of Creep Threshold Stress	262
19.6 The Experimental Results for Creep Crack Growth	264
References	272
20 Creep Damage Mechanics	274
20.1 Introduction to the Damage Mechanics	274
20.2 Damage Variable and Effective Stress	275
20.3 Kachanov Creep Damage Theory	277
20.4 Rabotnov Creep Damage Theory	279
20.5 Three-Dimensional Creep Damage Theory	281
References	283
21 Creep Damage Physics	285
21.1 Introduction	285

21. 2	Loss of External Section	286
21. 3	Loss of Internal Section	287
21. 4	Degradation of Microstructure	289
21. 5	Damage by Oxidation	295
	References	296
22	Prediction of Creep Rupture Life	297
22. 1	Extrapolation Methods of Creep Rupture Life	297
22. 2	$\theta$ Projection Method	300
22. 3	Maruyama Parameter	302
22. 4	Reliability of Prediction for Creep Rupture Property	304
	References	306
23	Creep-Fatigue Interaction	307
23. 1	Creep Fatigue Waveforms	307
23. 2	Creep-Fatigue Failure Maps	307
23. 3	Holding Time Effects on Creep-Fatigue Lifetime	310
23. 4	Fracture Mechanics of Creep Fatigue Crack Growth	312
	References	317
24	Prediction of Creep-Fatigue Life	319
24. 1	Linear Damage Accumulation Rule	319
24. 2	Strain Range Partitioning	321
24. 3	Damage Mechanics Method	324
24. 4	Damage Function Method	326
24. 5	Empirical Methods	328
	References	329
25	Environmental Damage at High Temperature	330
25. 1	Oxidation	330
25. 2	Hot Corrosion	338
25. 3	Carburization	342
	References	347
	<i>Appendix A</i>	349
	<i>Appendix B</i>	357
	<i>Index</i>	359

# **Part I**


## High Temperature Deformation

---



## 1.1 Creep Curve

The time-dependent plastic deformation of materials under constant stress at elevated temperature is called creep. In creep test, a constant load or a constant stress is applied to the specimen and the change of strain is recorded as a function of time. Figure 1.1 shows a typical creep curve schematically. As can be seen, there are three stages of creep. In the first stage, called primary creep, creep rate decreases with time. The second stage, called steady state creep or secondary creep, is characterized by a constant creep rate. In the third stage, called tertiary creep, creep rate increases with time, eventually leading to fracture.




1.1 Typical creep curve at constant stress.

This type of behavior can be explained by simultaneous occurrence of strain hardening and dynamic recovery at elevated temperature. At the beginning of creep, the deformation resistance is small and the strain rate is high. In primary creep, strain hardening causes the creep rate to decrease with strain. With increasing strain hardening, the rate of dynamic recovery is increased. The steady state creep will be reached when the strain hardening is balanced by the recovery softening. The tertiary creep, where creep rate increases (or flow stress decreases) with time, is primarily attributed to localized necking and also to the formation of creep cavities. Many commercial alloys, when tested in tensile creep, exhibit a large tertiary creep and no (or vary short) secondary stage is observed. In such a case the minimum creep rate is used to characterize creep properties. The absence of steady state creep is

## 4 High Temperature Deformation and Fracture of Materials

attributed to structural instability, for example particle coarsening and grain growth.

If the material is tensioned at a constant strain rate and the change of flow stress is recorded as a function of strain, then another type of deformation curve is obtained as shown in Fig. 1. 2. The constant strain rate deformation can also be divided into three stages. The flow stress increases with strain in the first stage; remains constant in the second stage and decreases in the third stage until fracture.



1. 2 Typical deformation curve at constant strain rate.

The two types of creep test, constant-load (or constant-stress) and constant-strain-rate creep, correspond to two engineering applications of materials at high temperature: long term services of components at constant load and hot processing at constant deformation rate, such as rolling, drawing and forging.

## 1.2 Stress and Temperature Dependence of Creep Rate

### 1. 2. 1 Stress Dependence of Creep Rate

Extensive phenomenological creep studies on polycrystalline metals indicate that the relationship between the steady state creep rate,  $\dot{\epsilon}$ , and the applied stress,  $\sigma$ , is described by the power law:

$$\dot{\epsilon} = A_1 \sigma^n \quad (1.1)$$

where  $A_1$  is a constant associated with temperature and material, and  $n$  is the stress exponent of creep rate. (From now on, the term “creep rate” will indicate steady state, or minimum, creep rate if there is no special notation). The value of  $n$  can be determined from the slope of  $\log \dot{\epsilon} \sim \log \sigma$  plot of experimental data at constant temperature. The value of  $n$  for pure metals in the intermediate stress range is usually equal to 5 (In the low stress range diffusional creep takes place and it will be discussed in Chapter 9). An example of this plot for pure aluminium is shown in Fig. 1. 3<sup>[1]</sup>. It can also be seen from the figure that the liner relationship between  $\log \dot{\epsilon}$  and  $\log \sigma$  (power law creep) in the intermediate stress range breaks down in the high stress range. This phenome-